

Wouldn't this normally be a drain? Why would it run up hill into the draft flow from the inducer fan?

Shouldn't this run to a condensate trap as shown by my blue line? Are they trying to pull the condensate up hill by venturi effect? Pushing Chain if You ask me.

